

Market Release Note

MRN-TS91016-V10-06

Product number: TS1016, TS1016B, TS1016SE, TS1016SEB

Product description: Challenger10, ChallengerSE

Product version: V10-06-8305

Affected parts: TS1016, TS1016B, TS1016SE, TS1016SEB

Release date: 5th June 2015

Resolved Issues

- Cards that have not been programmed into Challenger can no longer be granted access on RAS doors. Note that this issue only applies to RAS doors on systems using the TS1084 Memory Expander. The fault does not occur for users accessing the system via PIN code.

Known issues

- Due to the major changes included in this release, any Challenger10 or ChallengerSE panel will be classed as a new panel type when updated to this firmware. This means that the panel record will need to be converted to the new type in the software (Security Commander, Titan, Forcefield). Please refer to the manuals or call support if further information is required.
- Non-pollled peripherals are not backed up or restored when using the SD card.

Downloads

- [Challenger firmware \(V10-06-8305\)](#)
- [Challenger firmware Titan \(V10-06-8305\)](#)